

Welding Quality Simulation




Welding lines
profile defects







Solution for defect:
Increasing 8mm
the welding chamber



Welding Quality



RED = Structural welding
BLUE = Not welded



Welding lines
profile without defects

